

Flat Helium Display Assembly Instructions


Note: Assembly is the same for all sizes of flat Helium displays




1. Assemble bungeed poles.




2. Connect large bungeed poles to corners, matching up stickers.




3. Attach feet, match up stickers.



4. Insert center support pole in holes in top and bottom curved poles.



5. Pull pillowcased graphic over the frame.



6. Zip up the bottom of the graphic.



7. Attach optional light clamps to the top bar in desired locations.
Tip: It is easier to do this before standing the display up.



8. Connect LED lights to the clamp.



Need Help?

